





When applying your FrontLine® Bldg. Products Inc. SDL grilles, the three most important factors to consider are:

- Temperature
- Bar Length (not too long)
- Clean Glass

Failure to follow ALL instructions will increase application failure rate and will void the warranty.

### **Required Materials:**

- Isopropyl Alcohol / Water Mixture (50/50)
- Alcohol Prep Pads (included)
- GAP Packets (included)
- Plastic Razor
- Lint Free Cloth
- Spacer Gauge (credit card or business card will work)
- Plastic Zip Ties
- J-Roller

NOTE: The optimum air temperature range for best tape adhesion is between 70- and 100-degrees F. The minimum required air temperature is 60-degrees F. SDL bars and glass surface must be within temperature range as well, and must remain at minimum temperature for 72 hours after application.

#### STEP 1: Glass Preparation \*IMPORTANT!\*

- Remove all stickers, silicone, or other debris from glass surface. If silicone was present, use an adhesive remover on the glass prior to wiping down with Isopropyl Alcohol / Water mixture.
- 2. Use plastic razor blade to remove any sticky residue.
- 3. Clean glass using a disposable, white, lint-free cloth soaked in the Isopropyl Alcohol / Water mixture. Thoroughly wipe the glass surface clean.

## STEP 2: Dry Fit SDL Bars to Glass Surface

- 1. Assemble the SDL kit.
- 2. Position bar on glass surface to ensure proper fitment.
- 3. There should be a minimum of 1/64" space between the end of the SDL bar and glass perimeter (about the thickness of a credit card).
- 4. If the gap is too tight, trimming the SDL to proper length is required. See "How to Trim SDL Bars for Proper Fitment" section below.
- 5. Once fitment is confirmed, move on to Step 3.

NOTE: Failure to properly prepare the glass surface will result in poor tape adhesion. The use of glass cleaner (Windex, etc.) is not a suitable substitute for the recommended procedure and will prevent the tape from properly adhering to the glass surface, resulting in failure.



### STEP 3: Final Glass Prep and Application \*IMPORTANT!\*

- 1. Open Alcohol Prep Pad provided and wipe glass surface.
- 2. Open GAP Packet and wipe the glass surface where the SDL bars will be applied.
- 3. Peel plastic film from back of tape.
- 4. Apply zip ties about 6" apart (or at each intersecting bar), starting 1" from the end work of SDL bar. See Figure A for zip tie placement.
- 5. Position the SDL bar on the glass surface, making sure to maintain a minimum 1/64" gap between SDL bar and lite frame (use the spacer gauge to assist).
- 6. Press down on the end of each of the SDL bars.
- 7. Slowly work your way along the SDL bar (removing the zip ties as you go) and press the SDL bar down to glass surface.
- 8. Once all the zip ties are removed, use the J-Roller and roll the SDL bars to the glass surface.
  - Start by rolling the outside edges of the SDL bar, working your way towards intersections
  - Use a minimum of 15 pounds of pressure, ensuring that the tape wets out.
  - Check wet out on opposite side of glass if possible. Wet out should be at least 50% after proper rolling (within 20 minutes, see Figure B).

Repeat this process for the other side of the glass.


# HOW TO TRIM ALUMINUM SDL BARS FOR PROPER FITMENT (IF REQUIRED): VISIT OUR YOUTUBE PAGE TO VIEW HOW-TO VIDEOS


Using a Disc Sander (Figure C):

- 1. Set the table to the appropriate angle.
- 2. Use a miter square and align SDL bar square to the disc sander.
- 3. Gently touch the SDL tip to the disc sander to remove required amount of material for proper fitment.

Using a Chop Saw (Figure D):

- 1. Set chop saw to required angle.
- 2. Use minimum 120-tooth carbide-tipped blade.
- 3. Place tape side of bar against miter fence and slowly cut SDL bar to appropriate size (recommend removing only 1/32" at a time).
- 4. Clean up any residue on tape left after trimming if needed.









# Connect with Us

- www.frontlinebldg.com
- SalesMedford@frontlinebldg.com
- 1-800-223-4792



